Reference No. 2

Rollins Environmental Services .. .. ......

One Rollins Plaza, P.O. Box 2349, Wilmington, Delaware 1989: (302) 429-2768

150 789



Rollins

Augsuts 27, 1985

Mr. Warren L. Smull Gen. Supt. Environmental Affairs Monsanto Industrial Chemicals Co., W. G. Krummrich Plant Sauget, IL 62201

Dear Warren,

Enclosed is a copy of our Health and Safety program for the NCB prum site on the Krummrich Plant site. I am also enclosing a copy of this program for Ken Storms.

Please do not hesitate to contact me if you have any questions.

Yours truly,

Paul A. B. Thomas

Paul A. B. Thomas Director, Health and Safety

PABT: jhm 0078t Enclosures

cc: Kenneth E. Storms

## MONSANTO INDUSTRIAL CHEMICAL COMPANY SITE SPECIFIC HEALTH AND SAFETY PLAN

SI	re: W.	G. Krumn	nrich	Plant	:		PROJECT	. ои	116-85	
Lo	cation:	Sauget	Illi	nois			Region:	Mid	l-West	
Cl	ient Co	ntact: V	larren	L. 9	Smull		Phone N	10: 6	18-271-	5835
Pl	an Prep	ared by:	Paul	а. в.	Thomas	s	Date:	7/22/	85	
Ob of ch	jective an est loroben	(s): Rem imated 4 zenes and	noval, ,500 1 500	r epa 55-9 80-	cking, allon gallon	tran drums drum	sportat of mon s of ni	ion a no and itrate	nd disp I dinitr ed biphe	osal o nyls.
Pro	posed	Date of A	ugust	1, 1	.985 th	rough	Novemb	er 30	, 1985	
Ba	ckgroun	d Review	is: C	omple	te	X		Preli	minary_	<del></del>
OV	erall H	azard is: L	.ow:	igh:_		X	Unkno	Moder	ate:	
SI: 20 so: the	TE DESC ft. dr ll and drums	RIPTION: um storag abandoned and the tasks:	The see/display	site posal t 194	consist /trench 6. The	ts of n Whi e unce	a 42 f ch was overing	t. x cover	248 ft. ed with removal	x
1.	equi	lize equi pment pri safety.								ion
2.	Remo	ve and st trench.	ore ti	he ra	ilroad	traci	ks pres	ently	crossin	ıg
3.	Unco	ver and e aminated anto.	xhume soil p	the plus	buried any add	drum: Biton	s, any al soil	visib as d	ly irected	ьу
4.	Stag	e drums a testing a							taging a	rea
5.	Open	each dru e for tra	m, rei	nove	the con	tents	s and r	epack	age the	
6.	Crusi	h the emp	tied	drums	in pre	para	tion fo	r tra	nsportin	ıg
7.	Pack:	age visib transport ntially c	ing ar	nd in	cinerat	ion;	stockp	ile a	dditiona	1
8.	Back:	fill the dirt to 2 compacted	excava ft. t	ted (	trench	with	compact	teď, i	nonselec	t
9. 10.	Hydro	omulch or ore the r	seed	all (	disturb acks to	ed ar	eas.	ondit	ion.	
11.	Decor	ntaminate	all e	quip	ment an	d den	nobiliz	е.	•	
REVIEW AND APPROVALS										
Project M	anager:	: Frank (	Gorry					Date	<u> </u>	
Health Sa	fety Ma	nager:	Paul A	. в.	Thomas			Date	e	

## List known substances on the site

1. Substance	2. Form	3. Toxicity	Amount* Unit	
	Solid Liquid Vapor	High Med. Low N	one	
Mono nitrochlorobenzene: and Di nitrochlorobenzenes	s) )	X 4,500	( 0-5%) drums( ) (95-100%)	
Mono ritrobiphenyls ** Biphenyl Unknown	) ) x	x 500	( 65%) drums( 21%) ( 14%)	

- \* See attached "Drum Analysis"
- \*\* Including 4-Nitrobiphenyl, an OSHA listed carcinogen.

WASTES TYPES:	Liquid: Sludge:	M.pt.95 <sup>0</sup> F	Solid: 5,00 Gas:	00 drums
CHARACTERISTICS:	Corrosive	Flamma	able	Radioactive
	Toxic X	Volatile _	Reactiv	re Inert

HAZARD ASSESSMENT

(See attached data sheets.)

Nitrochlorobenzenes may be absorbed through the skin, by inhalation, or ingestion; they affect the ability of blood to carry oxygen by forming methemoglobinemia. A bluish discoloration of the skin (starting with the lips) may occur with headache, irritability, dizziness, weakness, nausea, vomiting, shortness of breath, drowsiness, and unconsciousness. The onset of symptoms may be delayed; alcohol may increase susceptibility.

4-Nitrobiphenol is an CSHA listed carcinogen known to cause bladder cancer in humans.

## MONSANTO, SAUGET SITE Proposed Work Area

